## **Slave Housing Data Base**

**Building Name:** Elk Hill Kitchen-Quarter – Building 1 (to north of Bldg. 2)

**Evidence Type:** Extant **Site ID:** 037-0009

Historical Site Name: Elk Hill

County: Goochland State: Virginia

Investigators: Douglas W. Sanford, Dennis J. Pogue

**Institutions:** Virginia Slave Housing Project

#### **Summary Description:**

This brick, four-bay, two-story structure has a side-gabled roof covered with slate shingles, and a central interior chimney that contains fireplaces for each of the building's four rooms. The exterior walls are laid in three-course common bond, with the front and rear walls capped with three-course corbelled eaves, characteristic of the Federal style. Two exterior doorways on the north façade provide separate access to each of the downstairs rooms. Originally, there was no access between the two rooms on either floor, with stairs rising along the end walls of the downstairs rooms to reach the heated rooms above.

At roughly 22 feet wide and 43 feet long, providing over 950 sq. ft. of space per floor, this structure represented a substantial investment. The rooms were well lit, with 14 large sash windows. The first floor rooms functioned as a kitchen (to the east) and a workroom to the west, possibly a laundry, with two quartering rooms upstairs. The kitchen fireplace measured over eight feet wide and likely incorporated an oven at one end, along with an elevated warming niche. The western downstairs room had a smaller fireplace, but with two large flanking closets, one with multiple shelves. The interior brick walls were finished with whitewash. Given its Federal period stylistic elements, the building likely dates to the 1820s.


The main plantation house is parallel and located within a few hundered feet of the kitchen-quarter. The brick house was extensively modified in the 1830s, when the walls were covered with stucco. When they were constructed, it is likely that the two buildings shared Federal style characteristics, such as corbelled eaves, which were modified or removed from the house.

The exterior walls of the oubuilding initially were convered with a yellow-tinted limewash, with the mortar joints penciled in with a red pigment. The walls later were covered with whitewash, followed by white paint in the post-Civil War era. Later changes included removing all original window sashes and doors, replacing the wood flooring, introducing modern utilities, and inserting a hot water heater adjacent to the


kitchen fireplace. The oririginal stairs also were removed and replaced, and door openings were inserted through the medial wall on both floors.

# **Principal Construction Type:** Brick **Two Story**

### First Floor Plan



## **Second Floor Plan**



**Number of Rooms:** 4 total (2 down, 2 up)

**Dimensions:** (1) Downstairs, east: 20.3.2 (N-S) x 19.11.2 (E-W), 9.1.2 (H)

(2) Downstairs, west: 20.1.2 (N-S) x 16.3.3 (E-W), 9.1.1 (H) (3) Upstairs, east: 19.9.2 (N-S) x 19.9.3 (E-W), 8.5.1 (H)

(4) Upstairs, west: 20.2 (N-S) x 17.4.3 (E-W), 8.5.1 (H)

**Doors:** 2 original doors measured; other interior doors are later insertions, as is the exterior door at the SE corner

	Rm. 1, N (1)	Rm. 2, N (2)
Type:	3 panel	2/2 panel
Dimensions:	2.11.3 (W) x 6.9.3 (H)	2.11.2 (W) x 6.7.2 (H) 0.1.1 thick
Hardware:	5 knuckle butt hinges	5 knuckle butt hinges
Swing:	In	In
Replacement:	Yes, modern	Yes, modern

**Windows:** 14 total; **N.B.** All original window sashes have been removed, replaced by 6/6 double-hung sash vinyl windows. The measurements below reflect the distances from surviving window headers to either surviving sills or estimated tops of sills (height); and, the distances from one brick wall surface to another, for the outsides of the original window frames.

	Rm. 1, N (1)	Rm. 2, N (2)	Rm. 1, E (3)
Type:	Sash (removed)	Sash (removed)	Sash removed
Dimensions:	3.4.3 (W) x 5.1.0 (H)	3.5.0 (W) x 4.10.0 (H)	3.5.2 (W) x 4.10.2 (H)
Hardware:	Unknown	Unknown	Unknown
Shuttered/ Slide/ Swing:	NA	NA	NA

Windows: continued

	Rm. 1, SE (4)	Rm. 1, SW (5)	Rm. 2, SE (6)
Type:	Sash (removed)	Sash (removed)	Sash (removed)
Dimensions:	3.5.0 (W) x 4.11.2 (H)	3.4.3 (W) x 4.11.0 (H)	3.5.0 (W) x 4.10.0 (H)
Hardware:	Unknown	Unknown	Unknown
Shuttered/ Slide/ Swing:	NA	NA	NA

	Rm. 2, SW (7)	Rm. 2, W (8)	Rm. 3, N (9)
Type:	Sash (removed)	Sash (removed)	Sash (removed)
Dimensions:	3.5.2 (W) x 4.10.0 (H)	2.11.0 (W) x 4.9.0 (H)	3.5.2 (W) x 4.8.2 (H)
Hardware:	Unknown	Unknown	Unknown
Shuttered/ Slide/ Swing:	NA	NA	NA

	Rm. 3, E (10)	Rm. 3, S (11)	Rm. 4, S (12)
Type:	Sash (removed)	Sash (removed)	Sash (removed)
Dimensions:	3.5.2 (W) x 4.10.2 (H)	3.5.1 (W) x 4.8.2 (H)	3.5.2 (W) x 4.8.0 (H)
Hardware:	Unknown	Unknown	Unknown
Shuttered/ Slide/ Swing:	NA	NA	NA

Windows: continued

	Rm. 4, W (13)	Rm. 4, N (14)
Type:	Sash (removed)	Sash (removed)
Dimensions:	3.5.2 (W) x 4.9.0 (H)	3.4.3 (W) x 4.8.0 (H)
Hardware:	Unknown	Unknown
Shuttered/ Slide/	NA	NA

#### **EXTERIOR**

**Swing:** 

#### Foundation:

Continuous Masonry: Brick

Thickness: 0.1.1 Bond: Common 3:1 Mortar Type: Sand Joint: Overhand struck

Repaired: Yes

Shed/Porch: No

**Roof:** 

Roof Form: Gable

**Roof Covering:** Slate shingles

Roof Framing: not exposed, not accessible

Building Height: @ NW corner

Ground to Corbel base: 18.9.0 Ground to Top of Eave: 19.7.3

Walls:

Masonry: Brick

Number of Courses: NA Bond: Common 3:1 Mortar Type: Sand Joint: Overhand struck

#### Repaired: Yes

Walls originally covered with yellow-tinted lime wash, and penciled red pigmented mortar joints.

#### Chimney(s):

Chimney (1):

Material: Brick

**Location:** Interior - Center **Height:** Not accessible

#### **INTERIOR**

Wall Framing: NA - brick Wall Finish: Whitewash

Fireplace (1): End – Center (Room 1, kitchen)

Fireplace Material: Brick

**Fireplace Overall Dimensions:** 8.5.0 (W, north-south)

Fireplace Opening Dimensions: 5.4.2 (W, at present) x 3.11.2 (H) x 2.4.0 (D);

original width: 8.6.0

Hearth Material: Unknown, removed (floor now lower)

Hearth Dimensions: Unknown

**Fireplace (2):** End – Center (Room 2, work room?)

Fireplace Material: Brick

**Fireplace Overall Dimensions:** 8.4.0 (W, north-south)

Fireplace Opening Dimensions: 3.2.0 (W, at present) x 2.7.0 (H) x 2.1.2 (D);

original width: 4.6.3

**Hearth Material:** Brick (modern replacement, original material removed) **Hearth Dimensions:** 4.6.3 (N-S) x 1.4.0 (E-W), from current fireplace front;

(3.0.2 (E-W) from original fireplace face)

**Fireplace (3):** End – Center (Room 3, east quartering room)

Fireplace Material: Brick

**Fireplace Overall Dimensions:** 7.9.0 (N-S) x 1.6.0 (E-W) **Fireplace Opening Dimensions:** Unknown, enclosed & covered

Hearth Material: Stone

**Hearth Dimensions:** 7.6.2 (N-S) x 2.4.0 (E-W)

**Fireplace (4):** End – Center (Room 4, west quartering room)

Fireplace Material: Brick

Fireplace Overall Dimensions: 7.9.0 (N-S) x 1.10.0 (E-W)

Fireplace Opening Dimensions: estimated, 3.1.0 (W) x 2.8.1 (H) x 1.1.0 (D)

Hearth Material: Unknown, removed

**Hearth Dimensions:** Unknown

Stairs: Yes, 2 stairways – one at each gable end; original stairs not surviving

**Type:** Unknown (likely open ladder)

**Stairwell Dimensions:** Room 1: 2.9.2 (W (east-west)) x 6.3.0 (L (north-south))

**Number of Treads:** Unknown **Stair Tread Dimensions:** Unknown

Subfloor Pit: No

Floor: Wood (upstairs); floorboards removed downstairs (now linoleum)

Floorboards Dimension: Approx. 1.0.0 wide

**Dating:** 

**Dendrochronology Date: NA Other Date:** Ca. 1820-1840

**Dating Evidence:** 

Saw Marks: Sash sawn

Nails: NA